

SC753204

Original post set 1821 by Laughlin with witnesses: 20" black oak N 8 E 9 links, 8" beech S 4 W 11 links. Legal Survey 6-1866 by Wm. Smith per Lawrence Township Legal Survey Book pg. 16 labels the corner "F" but gives no details. Legal Survey 11-1880 by Fatout per Lawrence Township Legal Survey Book pg. 39 and 52 shows the corner and gives distances to the E and W but gives no detail on the corner itself. May, 1930 survey of Fort Benjamin Harrison boundary by George G. Schmidt, Inc. appears to show the corner with distances to the N and W. No detail is given on the corner itself. January 22, 1976 ties by Miller called for a 'square cut stone' marked U.S.M.R. XXVII. Ties were redrawn in February 1981. Survey of Fort boundary sertified November 16, 1981 by Schneider (Schneider Engineering) also notes the corner as being a stone monument chiselled "USMR XXVII". Distance and bearing are given tyo adjacent corners on the Fort boundary. Distances do not check with the 1930 survey. Re-tied September 13, 1982 by Wilcoxen. Re-tied 3-7-91 by Wilcoxen. Re-tied 12-13-99 by Wilcoxen.

REF.	DISTANCE	DESCRIPTION	
1.	27.62'	Boat spike E 24" thorn 20"up	
2.	14.05′	NW corner of sidewalk	
3.	60.13'	Top nut of fire hydrant	
4,	12.17'	Boat spike N 10" thorn 12"up	
5.	55.75′	Due W to "boundary stone found"	
6.	10.16′	Boat spike NE 8" hackberry 12"up	
		The state of the s	
			